



HARDWARE QUINCAILLERIE




A

x1



B

x2



C

x2



D

x10
M8*50



E

x10
M8*13



F

x10
M8*19




G


x1
M4*110

STEP 1

D = 6 pcs
E = 6 pcs
F = 6 pcs
G = 1 pc




STEP 2



STEP 3

D = 4 pcs
E = 4 pcs
F = 4 pcs
G = 1 pc



STEP 4

